

## Challenge exercise: Part inspection

The challenge: Create a probe operation to set the WCS location for the file *Headlight Mold.f3d*. Then, create inspection records to validate the machined part.

- Part Inspection

### Complete the required activities:

- Use probing to set the WCS location.
- Evaluate program prove out.




Figure 1. *Headlight Mold.f3d*.