

Challenge

Challenge: Create an inch CAM setup for the supplied file *complex socket - wc.f3d*. Create a new milling setup. Create all toolpaths needed to cut the geometry.

The following steps/items are required:

- Create a new milling setup.
- Create toolpaths of your choice to rough and finish the part.
- Use tools from the sample library that can cut all geometry.
- Simulate the toolpaths.
- Post NC code.

